7155 0044

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RVS

inspection report

Permit No. ACT/015/019

Inspection Date July 21, 1989

Permittee/Operator Name Utah Power & Light Mining Division

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other

County Emery State

Company Official(s) Guy Davis

State Official(s) Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection June 29, 1989 Weather conditions Hot/Dry

Acreage 11508 ☐ Permitted 42.5 ☐ Disturbed ☐ Regraded ☐ Seeded 42.5 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 7/21/89

Please number comments to correspond with topics on previous page.

General Comments. With the switch of mines, this was my first inspection of the Cottonwood/Wilberg Mines for about a year and a half. The operator has made many environmental improvements since my last inspection. This partial inspection concentrated on field checking against the records the permit boundary & access signs; disturbed permitter markers and the disturbed area, including SAE's; sediment control measures.

Permit. Permit is in the process of renewal. Some minor changes to the permit map are being considered by the operator that may assist an uninformed reader. No disturbance was observed outside the permit or disturbed area markers.

Signs & Markers. Required signs and markers are in place. Some followup work is being considered by the operator on the main access sign & waste rock disposal area.

Other Sedmiment Control. Operator stated that the silt fences near the guard station are scheduled for routine replacement. The silt fences are functional, but the top has wind/sun damage.

Copy of report mailed to SLC: Brain Smith/OSM; Joe Helfrich/DOGM

Copy of report given to Guy Davis UP&L

Inspector's signature Tim J. Malenich No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

7/21/89.

DOGM/IR-2 an equal opportunity employer 11/86 001049