0030

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340



# inspection report

Permit No. ACT/015/019

Inspection Date May 22, 1990

Permittee/Operator Name Utah Power & Light Co.

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Harry Guymon.

State Official(s) Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 4/19/90 Weather conditions Clear / Warm / Dry Mine Site

Acreage 11508 ☐ Permitted 42 ☐ Disturbed ☐ Regraded ☐ Seeded 42 ☐ Bonded

Enforcement Action None.

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☐ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| — Stream channel diversions | ☒ | ☐ | ☐ | ☐ |
| — Diversions | ☒ | ☐ | ☐ | ☐ |
| — Sediment ponds and impoundments | ☒ | ☐ | ☐ | ☒ |
| — Other sediment control measures | ☒ | ☐ | ☐ | ☒ |
| — Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| — Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☒ | ☐ | ☐ | ☒ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☒ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☒ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☐ | ☐ | ☐ | ☐ |
| — Drainage controls | ☒ | ☐ | ☐ | ☐ |
| — Surfacing | ☐ | ☐ | ☐ | ☐ |
| — Maintenance | ☒ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☒ | ☐ | ☐ | ☐ |

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 5/22/90

Please number comments to correspond with topics on previous page.

General Comments: Guy Davis nor Val Payne were at the engineering office. Advised Debra, the secretary, that I was conducting a partial inspection on Cottonwood. Went to the mine and Harry Guymon accompanied the undersigned on the inspection at the main mine site; I went alone to the Cottonwood Fan Portal area.

No significant problems of an environmental nature were observed at either of the aforementioned sites.

Sediment Ponds: Both ponds contained water, were stable and not discharging.

Other Sediment Control: The operator since the last inspection had upgraded the silt fences adjacent to the Deer Creek Portals.

The sediment trap by the fan near the Deer Creek Portals had also been worked on since the last inspection. The berm height had been increased providing adequate freeboard & capacity.

Silt fences, shall bales and other sediment control

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. Act/015/019

Inspection Date 5/22/90

Please number comments to correspond with topics on previous page.

measures on the site looked good and were all in a fully functional mode.

Development Waste. Material primarily waste rock was being stored on the lower cell. Some non coal waste had been segregated from the waste rock and it will be removed to a landfill.

The operator continues working on providing necessary documents for permitting a new waste rock site.

Copy of report mailed to UP&L/Guy Davis; SLC For: OSM/Brian Smith; DOGM Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature M. J. Malencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

5/29/90

DOGM/IR-2

an equal opportunity employer

11/86 001049