0035

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gck pgl

inspection report

Permit No. ACT/015/019

Inspection Date 3/8/90

Permittee/Operator Name Utah Power & Light Co

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Guy Davis & Blake Webster

State Official(s) Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection Feb. 15, 1990 Weather conditions Pt Cloudy/Cold.

Acreage 11508 ☐ Permitted 42 ☐ Disturbed ☐ Regraded ☐ Seeded 42 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 3/8/90

Please number comments to correspond with topics on previous page.

GENERAL COMMENTS. Blake Webster, UP&L mgt trainee accompanied Guy Davis and the undersigned on this inspection.

I was advised that the name of the mine is now Cottonwood and the name Wilberg has been dropped from the title. Not officially, however.

Signs & Markers.

I.D signs on the waste rock site were again discussed. Signs have not yet been placed at each access from a public road to the waste rock sites. However the operator has moved the sign as previously instructed by the Division, which is not considered inappropriate. Rather than moving the existing sign, the operator plans to add additional signs at each access point off a public highway.

Some minor adjustments were suggested on the disturbed markers in the vicinity of the right fork of Quinnes Wash.

Other Sediment Control. The operator was working on the sediment control measures on (1) the three Deer Creek Portals and (2) The sediment basin below the reclaimed road to the Deer Creek Portals

Copy of report mailed to UP&L/ Guy Davis/ SLC For OSM/Brian Smith/DOGM-Joe Helfrich

Copy of report given to filed RFO

Inspector's signature Tom J. Chalmick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

3/12/90

DOGM/IR-2

an equal opportunity employer

11/86 001049