



NO. N 91-32-3-1

To the following Permittee or Operator:

Name Pacific Electric Operations

Mine COTTONWOOD/WILBERG Surface Underground Other

County EMERY State UTAH Telephone 220-4621

Mailing Address 324 SOUTH STATE STREET, P.O. BOX 26128

State Permit No. ACT/015/019

Ownership Category State Federal Fee Mixed

Date of inspection MARCH 27, 1991, 19 91

Time of inspection 9:30 a.m. p.m. to 12:30 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing MARCH 28, 1991 Time of service/ mailing 1:30 a.m. p.m.

BLAKE WEBSTER
Permittee/Operator representative

[Signature]
Signature

Permitting Administrator
Title

HENRY SAUER
Division of Oil, Gas & Mining representative

[Signature]
Signature

Reclamation file specialist
Title

#32
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 91-32-3-1

Violation No. 1 of 1

Nature of violation

Failure to control or prevent erosion and failure to control or prevent additional contributions of suspended solids to stream flow.

Provisions of act, regulations or permit violated

*R 614-301-752.210
R 614-301-752.220
U.C.A 1953 ET. SEC. 40-10-18⁽²⁾(i)(ii)*

Portion of operation to which notice applies

The outslope of the access/haul road from the permit area/^{boundary} mine entrance gate to a point approximately 650 feet north of the entrance gate (north end of the guardrail).

Remedial action required (including any interim steps)

Interim Abatement: Provide interim sediment control measures to include: siltation structure at the bottom of the road outslope; stabilization of rills and gullies (i.e. placement of straw and rocks within the rills and gullies and seeding of said rills and gullies in accordance with the approved plan)

Final Abatement: Submit to the Division plans to provide adequate drainage controls for the section of the access road from the stop sign to the entrance gate and for the above referenced effected areas.

Abatement time (including interim steps)
NO Later than 5:00 P.M. APRIL 26, 1991