

0001



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

[Handwritten signature]

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: X Complete: Exploration:
Inspection Date & Time: 1/26/93 / 3:00pm - 5:00 pm
Date of Last Inspection: 12/22/92

Mine Name: Cottonwood/Wilberg County: Emery Permit Number: ACT/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, Utah 84528
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Official(s): Tom Munson
Company Official(s): Chuck Semborski, Karl Housekeeper
Federal Official(s): None
Weather Conditions: Clear and cool
Existing Acreage: Permitted-11,532 Disturbed-102 Regraded- Seeded- Bonded-102
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019 DATE OF INSPECTION: 1/26/93

(Comments are Numbered to Correspond with Topics Listed Above)

4d. Water Monitoring- The operator is in the process of compiling the necessary data to address PHC concerns associated with the mining of the Rilda Canyon Lease Extension. This process has involved drilling five ground water monitoring wells up Cottonwood Canyon. The inspection of these wells involved site monitoring of water levels and discussing the peticular installation and completion problems. The wells will be monitored as part of the established monitoring program for the Pacicorp mines.

The sediment ponds at the mine site were visited and the fourth quarter water monitoring data had not been compiled so no data was reviewed at the time of inspection. The ponds were frozen with only a small flow coming into the ponds. The ponds appeared very stable from a visual standpoint.

13. Revegetation - The drill sites up Cottonwood canyon will be reclaimed as soon as weather permits in the spring. The sites are currently under 2 - 4 feet of snow.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Karl HouseKeeper(PacifiCorp)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Thomas Munson # 25 Date: 1/29/93