

0015



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten signature

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 0900 to 1100, 5 May 1993
Date of Last Inspection: 24 March 1993

Mine Name: Cottonwood/Wilberg County: Emery Permit Number: ACT/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, Utah 84528
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Hugh Klein
Company Official(s): Karl Housekeeper Federal
Official(s): None
Weather Conditions: Clear and cool
Existing Acreage: Permitted-11,532 Disturbed-102 Regraded- Seeded- Bonded-102
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include items like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) 5 May 1993 (date); AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 5 May 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4b)

Both the north and south sediment pond were inspected. At the time of the inspection, no compliance problems were observed. The north pond had been cleaned recently.

4c)

Silt fences along the east side of the haul road adjacent to the gate were inspected and found to be in good order. In addition, the silt fences along the road to the waste rock site were also found to be in good order.


7)

The sediment pond cleanout material that was disposed of at the waste rock site had been placed in a controlled manner.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Karl Houskeeper(PacifiCorp)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: 

_____ Date: 5 May 1993