0019

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act/015/019
Inspection Date Feb 25, 1993

Permittee/Operator Name PacifCorp
Business Address P.O. Box 1005
City Huntington State Ut Zip 84528
Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Karl Houskeeper
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/26/93 Weather conditions Cloudy
Acreage 11532 ☐ Permitted 102 ☐ Disturbed ☐ Regraded ☐ Seeded 102 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/019

Inspection Date 2/25/93

Please number comments to correspond with topics on previous page.

General Comments. The mine site was covered with snow. Snow had been removed from the disturbed operational areas. The snow removed was relocated so that it would drain into approved runoff treatment devices.

Signs & Markers. Observed I.D sign at the end of the public road.

Sediment Pond. Observed the north and south pond at the mine site. Ponds were partially filled and ice covered. Did not observe the sediment pond at the refuse site. The late winter-early spring thaw has not taken place. No runoff was observed in the two major undisturbed drainages.

Roads. The roads were dry and snow had been removed on all roads used to haul coal.

Copy of report mailed to PC/ Karl Houskeeper; OSM/ Brent Smith; DOGM/ Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

2/26/93.