



inspection report

Partial Inspection Date: December 6, 1994
 Complete Time: 8:30 am pm to 10:30 am pm
 Exploration Date of Last Inspection: 11/16/94

Mine Name: Cottonwood/Walberg County: Emery Permit Number: Act 015/015

Permittee and/or Operator's Name: Pack Corp.

Business Address: P.O. Box 1005, Huntington, UT 84528

Type of Mining Activity: Underground Surface Prep. Plant Other

State Official(s): BILL MALENCIK

Company Official(s): KARL HOUSKEEPER

Federal Official(s): N/A

Weather Conditions: Cloudy / Skiff snow / some melting wet roads, pads / cloudy

Existing Acreage: Permitted- 11532 Disturbed- 102 Regraded- _____ Seeded- _____ Bonded- 102

Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____

Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 015/019

Inspection Date 12/6/94

Please number comments to correspond with topics on previous page.

General Comments. Partial inspection included mine site, active waste rock site and cottonwood area.

No on the ground activities were observed at the Cottonwood drainage area. This comment is included herein as related to the amendment submitted relating to the Cottonwood Mine breakout and surface disturbance and facilities to be constructed in connection therewith. The operator stated they had responded to the Division's deficiency letter. They are anxious to secure an approval of this amendment.

Sediment Pond. Both the N&S ponds contained water. Inquired about the pending determination by MSHA whether the ponds are governed by MSHA impoundment criteria. This has been pending since January 1993. PacifiCorp through their safety engineer, Randy Tethow has provided repetitive information to MSHA requesting a MSHA impoundment decision. To date the matter is still pending. Advised PacifiCorp to provide me with some key documents and I would try to assist them in resolving this matter. Advised Tom Munson of the current status since he was involved in this project.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 12/6/94

Please number comments to correspond with topics on previous page.

Water Monitoring. Mine water was being discharged from two approved sources.

Other Sediment Control. Observed silt fences at the mine and waste rock site.

Explosives. As mentioned in the prior inspection, explosives are now stored at the mine site. Since the last inspection additional signs have been installed at both the powder and cap storage areas.

Refuse Pile. As mentioned in the last inspection another left on the refuse pile has been completed and a new left started.

During the inspection the outslope of the completed left had been topsoiled. The topsoiled area was being seeded and matting installed on the topsoiled and seeded outslope. About half of the work was completed. Workers were on site doing the aforementioned work during the inspection.

Copy of report mailed to PC/Karl Houskeeper; OSM/Marcia Petta; DOGM/Joe Helfrich

Copy of report given to File PFO

Inspector's signature Tom J. Chalovich No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE