



**State of Utah**  
 DEPARTMENT OF NATURAL RESOURCES  
 DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210  
 PO Box 145801  
 Salt Lake City, Utah 84114-5801  
 (801) 538-5340 telephone  
 (801) 359-3940 fax  
 (801) 538-7223 TTY  
 www.nr.utah.gov

Michael O. Leavitt  
 Governor  
 Robert L. Morgan  
 Executive Director  
 Lowell P. Braxton  
 Division Director

1027

OK

**INSPECTION REPORT**

Partial XXX Complete \_\_\_\_\_ Exploration \_\_\_\_\_  
 Inspection Date: 11/20/2002 / Time: 9:30 to 12:30  
 Date of Last Inspection: 10/31/2002

Mine Name: Cottonwood/Wilberg Mine County: Emery Permit Number: C/015/019  
 Permittee and/or Operator's Name: PacifiCorp  
 Business Address: P.O. Box 310, Huntington, Utah 84528  
 Company Official(s): Dennis Oakley State Official(s): Joe Helfrich  
 Federal Official(s): None Weather Conditions: 55, sunny, windy  
 Type of Mining Activity: Underground XXX Surface \_\_\_\_\_ Prep Plant \_\_\_\_\_ Other \_\_\_\_\_  
 Existing Acreage: Permitted 11532 Disturbed 102 Regraded \_\_\_\_\_ Seeded \_\_\_\_\_  
 Status: Temporary Cessation

**REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT  
(Continuation Sheet)

PERMIT NUMBER: C/015/019

DATE OF INSPECTION: 10/31/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

There are two amendments pending: MT02, the Cottonwood midterm review, a deficiency response was sent on 10/30/2002, I was provided with three copies of the permittee's response to the remaining deficiencies; and BR00D, the Phase one bond release for the Cottonwood Fan Portal area. A deficiency response was sent on 10/22/2002, due on 01/22/2003. Inspections will be conducted on a quarterly basis. Recent correspondence to the Division dated 5/22/2001 described the status of the mine.


**2. SIGNS AND MARKERS**

Permit entry signs were in place for the Cottonwood mine.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

Additional work to the silt fence and gabions located below the Cottonwood sediment pond has been completed. Maps have been revised to accurately delineate the ASCA.

Inspector's Signature: \_\_\_\_\_

  
Joseph C. Helfrich #1

Date: November 25, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Chuck Semborski, PacifiCorp  
Price Field office

O:\015019.CWW\Compliance\2002\P\_1120.doc