



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director
 LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor
 GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Guy Davis Environmental Scientist
OGM	Joe Helfrich Environmental Scientist III

Inspection Report

Permit Number:	C0150019
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, December 01, 2004
Start Date/Time:	12/1/2004 9:30:00 AM
End Date/Time:	12/1/2004 3:00:00 PM
Last Inspection:	Tuesday, September 28, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny, 25

InspectionID Report Number: 473

Accepted by: whedberg
 12/9/2004

Permitee: **PACIFICORP**
 Operator: **ENERGY WEST MINING CO**
 Site: **COTTONWOOD/ WILBERG**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

6,886.88	Total Permitted
62.82	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a complete inspection of the Cottonwood Wilberg facilities. There were no compliance issues.

Inspector's Signature

Joseph C. Helfrich
 Joe Helfrich, Environmental Scientist III
 Inspector ID Number: 1

Date Monday, December 06, 2004

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150019
 Inspection Type: COMPLETE
 Inspection Date: Wednesday, December 01, 2004

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permit was renewed on August 10, 2004. The application for permit renewal was received May 10, 2004.

2. Signs and Markers

Permit entry signs were in place for the waste rock sites, Cottonwood Fan portal, sewer adsorption field, and facilities. Disturbed area markers were noticed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds and waste rock site were inspected on 10/04/04 for MSHA, and 11/08/04 for SMCCRA requirements. The ponds showed no hazards or signs of structural weakness. Silt fences and sediment basins were adequately functioning.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences were installed at the base of the two reclaimed catch basins at the Fan portal. The upper one has undergone some minor adjustment. Diversion ditch UD-3 is partially self reclaimed, partially breached, and partially maintained. The permittee has proposed to leave the ditch as is. It is questionable as to whether the current regulations allow the permittee to leave the ditch in the current condition. Mr. Oakley indicated that previous negotiations with the Division allowed the company to leave the ditch after reclamation. Mr. Davis and I discussed the components of an amendment to remove the silt fences at the entrance to the waste rock site. They included calculations using sedcad and rusle applications, some minor text changes, and possibly an ocular estimation of % cover. As of the date of this inspection, the permittee does not intend to remove the structures.

4.d Hydrologic Balance: Water Monitoring

Water monitoring has been completed for the third quarter of 2004, data entry will be completed by the end of December 2004.

4.e Hydrologic Balance: Effluent Limitations

Hard copies of the DMR's were current through October 2004.

7. Coal Mine Waste, Refuse Piles, Impoundments

John Christensen inspected the refuse pile on 10/04/04. The pile is at 36% capacity and currently is only being used for sediment pond clean out.

8. Noncoal Waste

The properties were clean of any garbage and paper waste.

15. Cessation of Operations

The mine site and fan portal are currently inactive.

Permit Number: C0150019
Inspection Type: COMPLETE
Inspection Date: Wednesday, December 01, 2004

Inspection Continuation Sheet

Page 4 of 4

16.a Roads: Construction, Maintenance, Surfacing

Repair work on the access road culverts inside the gate had been completed.

21. Bonding and Insurance

The liability insurance is current through 4/1/05.