

0035



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

12-21-87

file

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

### INSPECTION REPORT

INSPECTION DATE & TIME: Nov. 30, 1987  
11:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Co-Op Mining Co.  
Business Address: P.O. Box 1245 Huntington, Utah 84528  
Mine Name: Bear Canyon Permit Number: ACT/015/025  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): Gerald Hansen and Mel Coonrod  
State Official(s): Harold G. Sandbeck and Bill Malencik  
Partial:  Complete:  Date of Last Inspection: Oct. 23, 1987  
Weather Conditions: Clear and cool  
Acreage: Permitted 900 Disturbed 10 Regraded  Seeded  Bonded 10  
Enforcement Action: \_\_\_\_\_

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( X )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NON-COAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( X )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( X )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( X )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( X )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( X )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION Nov. 30, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Mel Coonrod (operator's consultant) and Gerald Hansen (Co-Op) accompanied the undersigned inspector on this partial. As of this date, Gerald Hansen will be responsible for Co-Op's environmental ground conditions.

On September 25, 1987, NOV 87-27-1-2 was issued by the undersigned inspector. Following is the NOV 87-27-1-2 status:

87-27-1-2, Part 1 of 2, which pertains to item 6 in the October 23, 1987, inspection report, has been extended to December 11, 1987. DOGM is reviewing submittal.

87-27-1-2, Part 2 of 2, which pertains to items 4, 5, 6, and 7 in the October 23, 1987, inspection report, has been extended to December 11, 1987. DOGM is reviewing submittal.

87-27-1-2, Part 1 of 2, which pertains to item 2 in the October 23, 1987 inspection report, has been extended to December 11, 1987. As of November 23, 1987, the operator was awaiting parts.

2. SIGNS AND MARKERS:

Perimeter markers are required to have orange tips. A few markers have yellow tips. The operator will make sure all markers have orange tips.

4b. DIVERSIONS:

Ditches: Operator was informed of ditches which require preventive maintenance.

Culverts: Operator was informed of a 24 inch culvert which needs a larger trash rack and preventive maintenance on outlet.

4c. SEDIMENTS PONDS AND IMPOUNDMENTS:

Operator was informed that pond inlet requires additional protection.

4d. OTHER SEDIMENT CONTROL MEASURES:

Operator was informed of berms which require preventive maintenance.

Copy of this Report:

Mailed to: Gerald Hansen and Mel Coonrod, Co-Op; Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Dec. 2, 1987