

0064



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

July 16, 1991

Mr. Wendell Owen
Co-Op Mining Company
P.O. Box 1245
Huntington, Utah 84528

Dear Mr. Owen:

Re: Division Order Item #3 of 18, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025-DO90A, Folder #2, Emery County, Utah

The revised Surface Facilities Map, 2-4A through 2-4D, and the Water Monitoring Map, 7-1A through 7-1D, designate areas which were disturbed prior to August 3, 1977. An aerial photograph of the permit area, taken in July 1976, indicates a smaller disturbance area than that shown on the maps. For example, no disturbance is indicated on the aerial photo of the upper storage pad, the portal access road (north of the coal storage area), and the southern coal storage pile adjacent to the water tank.

Due to these discrepancies, Co-Op Mining Company must provide documentation for the appropriate pre-1977 disturbance boundaries. Please submit this information to the Division, as soon as possible, no later than July 23, 1991, because this information is fundamental in the review of highwalls.

Sincerely,

A handwritten signature in cursive script, reading "Pamela Grubaugh-Littig".

Pamela Grubaugh-Littig
Permit Supervisor

jbe
cc: Kim Mangum
Susan White
AT015025.6