CO-OP MINING CO.
MINE WATER SURVEY
SCALE: 1" = 500'
DRAWN BY: C. Reynolds
DATE: 01-01-00
BEAR CANYON
PLATE 7-10B
Note: Mine Fan was out of service, preventing access during water survey. Information shown is from 1995 Mine Water Survey.
HIAWATHA SEAM
STRIKE - N 19° 45'
DIP 2°
LEGEND
PERMIT BOUNDARY
COAL OUTCROP
MINE WATER LINE
WATER SAMPLE POINT
SBC-9
STANDING WATER
ROOF DRIPPERS
FLOOR SEEPS
MINE WORKINGS
PILLARED AREA
FAULT
LOW COAL
AREA
FAULT
5' OFFSET
SEEP FROM FAULT
<0.1 GPM
ROOF DRIPPERS
<0.1 GPM
FAULT
UP 150-200'
FAULT
UP
DOWN
FAULT
UP
DOWN
UP 20'
DOWN
UP 2' FAULT
DOWN
UP 4' FAULT
DOWN
2324
2625
13
14
23
24
N
LICENSED PROFESSIONAL ENGINEER
CHARLES REYNOLDS
No. 179670
DATE
SIGNATURE
N 400,000
N 395,000
N 394,000
N 393,000
N 392,000
N 391,000
N 390,000
E 2,111,000
E 2,112,000
E 2,113,000
E 2,114,000
E 2,115,000