

2000 Annual Report Review

Permittee: Co-Op Mining Company
Mine Name: Bear Canyon Mine
Permit Number: C/015/025
Date Report Received: 4-6-01

Assigned Reviewers: Pete Hess, Engineering *pete*
Jim Smith, Hydrology/Inspector *JS*
Joe Helfrich *JH*

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

Assignments:

- Inspectors:** Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.
- Hydrologists:** Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste
- Biologists:** Review Vegetation/Revegetation Success Monitoring, Raptor Survey
- Engineers:** Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden, Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Cover Sheet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Appears adequate
AVS; Legal/ Financial Update	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Appears adequate
Mine Sequence Map	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plate 3-4C shows retreat mining in Bear Canyon #2 Mine (Tank Seam) through 2000. Plate 3-4A shows both development and retreat mining through 2000 in the Blind Canyon seam. No mining occurred in the Hiawatha seam during the year 2000 (Plate 3-4B) Maps are certified by Charles Reynolds, P.E
Water Monitoring Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Precipitation & Climatological Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Precipitation only
Non-Coal Waste report	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No report on abandoned underground equipment or other non-coal waste
Subsidence Monitoring Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The permitte monitors 23 points relative to the Bear Canyon and Trail Canyon Mines. All points reported less than one foot of settling or heave over the past year. Both the reported data and the included subsidence map are P.E. certified by Mr. Charles Reynolds.
Annual Impoundment Certification	<input type="checkbox"/>	<input checked="" type="checkbox"/>	All pond annual impoundment certifications are on file in UDNR/OGM/SLO. None were included with the annual report

2000 Annual Report Review

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Annual Overburden, Spoil, Refuse, Floor, etc.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not required
Vegetation Data	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not required
Revegetation Success Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not required
Raptor Survey	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not required
Other Information	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

O:\015025.BCN\FINAL\AR_2000.doc