

Table 7-15 Past and existing monitoring sites

Site ID	Description	Status
Springs		
SBC-1	Under Ground Seep <sup>1</sup>	Dried up early 1988, and monitoring was discontinued.
SBC-2	Portal Well <sup>2</sup>	Dry from 1987. Caved in, lost (2) quarters and relocated in 1991.
SBC-3	Creek Well	Active
SBC-4	Huntington Spring	Active
SBC-5	Birch Spring	Active
SBC-6	COP Development Spring <sup>3</sup>	Dried up in 1987, with no flow through 2000. Monitoring discontinued in 2000.
SBC-12	Bear Creek Source (16-7-13-1)	Active
SBC-14	Right Fork Spring WHR-6	Active
SBC-15	Right Fork Spring WHR-5	Active
SBC-16	Fish Creek Spring WHR-4	Active
SBC-17	Upper Bear Spring 16-7-24-4	Active
SMH-1	MH Left Fork Spring (FBC-6)	Active
SMH-2	MH Water Trough (FBC-5)	Active
SMH-3	MH/Trail Ridge Spring (FBC-13)	Active
SMH-4	MH Right Fork Spring (FBC-4)	Active
In-Mine Sources		
SBC-7	Sump #1	Dried up and discontinued in 2000.
SBC-8	Sump #2	Dried up and discontinued in 2000.
SBC-9	Sump #3 <sup>4 6</sup>	Abandoned in 1999 due to retreat mining and replaced by SBC-13.
SBC-9A	Hiawatha Seam 1 <sup>st</sup> North	Activated in Oct. 2002 when a borehole was drilled up to the old SBC9 site. A pipe was laid from this site to the portal when the mine was sealed.
SBC-10	Sump #4	Flow first measured Dec. 1991. Monitoring initiated Jan. 1992. In July, 1995, retreat mining progressed passed this sump, making it inaccessible. Monitoring was discontinued in August 1995. Flows from this area have subsequently flowed through the pillared area and out of the 1 <sup>st</sup> East pillared section.
SBC-11	Hiawatha Seam 1 <sup>st</sup> North	Abandoned in April 2002 due to a roof fall. Water flows to SBC-9A
SBC-13	1 <sup>st</sup> East Pillared Section <sup>5</sup>	Abandoned in April 2002 due to retreat mining and replaced by SBC-9A
Wells		
DH-1A	2nd W. Monitor Well	Abandoned in 2001 due to retreat mining.
DH-2	3rd W. Monitor Well <sup>6</sup>	Abandoned in 1999 due to retreat mining.
DH-3	1st E. Monitor Well <sup>6</sup>	Abandoned in 1993 due to retreat mining and was replaced by DH-4.
DH-4	3rd W. Bleeder Monitor Well <sup>6</sup>	Abandoned in 1999 due to retreat mining.
SDH-2	Well, Sec. 11, T16S, R7E	Active
SDH-3	Well, Sec. 10, T16S, R7E	Active
MW-114	Wild Horse Ridge Monitor Well	Active
MW-117	Gentry Mtn. Monitor Well	Active