

UNITED STATES DEPARTMENT OF THE INTERIOR

Office of Surface Mining
Reclamation and Enforcement

Originating Office: OSM
Albuquerque Field Office
219 Central Ave NW #216
Albuquerque NM 87201

RECEIVED
APR 30 1985

TEN-DAY NOTICE 0014

Number: X 8501 02-113-05 TV 1

Telephone Number: 505
766 8075

Ten-Day Office to the State of UTAH

You are notified that, as a result of Federal Inspections (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Genwal Coal Company County: Emery Surface
(Or Operator if No Permit)
Mailing Address: PO Box 1201 Huntington UT 84378 Underground
Permit Number: ACT/015/032 Mine Name: Crandall Canyon Mine Other

NATURE OF VIOLATION AND LOCATION: Surface
Surface
by reports CB

Section of State Law, Regulation or Permit Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: Copies of records are not available for review: as-built pond certification and surface blasting reports.

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 840.12(b)

NATURE OF VIOLATION AND LOCATION: **RECEIVED**

APR 30 1985

Section of State Law, Regulation or Permit Condition believed to have been violated:

Remarks or Recommendations:

Date of Notice: 4/26/85

Signature of Authorized Rep.: Charles Bodner

Print Name and ID: CHARLES BODNER #113