

0002

1-26-88

File

SC



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 21, 1988
10:00 AM to 12:00 M.

Permittee and/or Operators Name: Genwal Coal Comapny
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official (s): Lannie Burnside; Surface Operator
State Official(s): James Leatherwood DOGM
Partial: XXX Complete: Date of Last Inspection: Dec. 16 & 17, 1987
Weather Conditions: cold
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action: NOV88-16-1-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/O15/O32

DATE OF INSPECTION 1/21/88

(Comments are Numbered to Correspond with Topics Listed Above)


1. Permit. NOV88-16-1-1 was issued for failure to submit a permit application package renewal at least 120 days before the expiration of the permit. The permit expiration date is May 13, 1988. The date 120 days prior to the expiration date is January 13, 1988. The abatement date of February 10, 1988 was agreed upon by both the operator and myself.

6. Disposal of Development Waste and Spoil. Approximately three-fourths of the waste that was temporarily stored on the loadout pad area has been removed and disposed of underground. The operator expects the rest of the waste to be removed and disposed of prior to the implementation of the coal processing and truck loadout facility construction.

Copy of this Report:

Mailed to: A. King- Genwal Coal; John Kathmann- OSM

Given to: J. Helfrich-DOGM

Inspectors Signature and Number:  #16 Date: 1/21/88