

0050

11-21-88
- 7050



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

SU

John

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 8, 1988
11 a.m. to 4:30 p.m.

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official (s): Lannie Burnside and Robert Gent
State Official(s): Harold G. Sandbeck
Partial: XXX Complete: Date of Last Inspection: October 30, 1988
Weather Conditions: Cold and wet. Snowing at times.
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action:

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	(XX)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	(XX)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION November 8, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. On this partial inspection both the Mohrland and Genwal sites were inspected. The undersigned inspector was accompanied by Lannie Burnside at the Genwal site and by Robert Gent at the Mohrland site.

4. Hydrologic Balance:

b. Diversions.

Genwal Site

The operator was informed that preventive maintenance is required on a ditch located north of the pond along the haul road. At this time a violation is not warranted.

Mohrland Site

The operator has been repairing the damage caused by the Utah Railway Company disturbance as mentioned in the previous inspection report. The operator has reinstalled the required berms and undisturbed drainage ditches. The operator intends to reinstall a swale to direct drainage into the sediment pond and dress up the pond inlet.

c. Sediment Ponds and Impoundments.

Genwal Site

The pond was not discharging. The operator intends to repair the small leak in the pond decant. The pond decant appears stable with no obvious signs of weakness. At this time a violation is not warranted.

The in-mine water was not discharging. The operator repaired the discharge valve which was defective.

The 1988 3rd quarter pond inspection was checked. The small leak had been noted by the operator. No other problems were noted.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION November 8, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

d. Other Sediment Control Measures.


Genwal Site

The operator was informed that a berm requires preventive maintenance. This berm is located below the reclaimed powder magazine area near the sediment trap. At this time a violation is not warranted.

Copy of this Report:

Mailed to: Andy King (Genwal Coal), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number:  #27 Date: 11/14/88