

3-15-89  
7050-

0009



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-27-4-1

notice of violation

To the following Permittee or Operator:

Name Genwal Coal Company

Mine Crandall Canyon  Surface  Underground  Other

County Emery State Utah Telephone \_\_\_\_\_

Mailing Address P.O. Box 1201, Huntington, Utah 84527

State Permit No. AET/OKS/032

Ownership Category  State  Federal  Fee  Mixed

Date of inspection March 7, 1989

Time of inspection 8:00  a.m.  p.m. to 5:00  a.m.  p.m.

Operator Name (other than Permittee) Andy King

Mailing Address Same As Above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing March 7, 1989

Time of service/ mailing 5:00  a.m.  p.m.

Andy King  
Permittee/ Operator representative  
Andrew King  
Signature

MINE MANAGER  
Title

Harold G. Sandbeck  
Division of Oil, Gas & Mining representative

Reclamation Inspector  
Title

Harold G. Sandbeck  
Signature

#27  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

~~200~~ 2716



NOTICE OF VIOLATION NO. N 89-27-4-1

Violation No. 1 of 1

Nature of violation

*m*

Failure to protect topsoil pile from water erosion.

Provisions of act, regulations or permit violated

UMC 817.23

Portion of operation to which notice applies

Topsoil Pile number 03 (Toe End)

Remedial action required (including any interim steps)

- 1) Redirect road drainage
- 2) Upgrade the straw bales

Abatement time (including interim steps)

April 7, 1989 by 5:00 pm