

7-31-89  
2050

0029



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-27-9-1

notice of violation

To the following Permittee or Operator:

Name Genwal Coal Company

Mine Crandall Canyon Mine  Surface  Underground  Other

County Emery State Utah Telephone 687-9813

Mailing Address P.O. Box 1201, Huntington, Utah 84528

State Permit No. ACT/015/032

Ownership Category  State  Federal  Fee  Mixed

Date of inspection July 27, 19 89

Time of inspection 10:06  a.m.  p.m. to 3:30  a.m.  p.m.

Operator Name (other than Permittee) Same As Above

Mailing Address " " "

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/~~mailing~~ July 27, 1989 Time of service/~~mailing~~ 3:30  a.m.  p.m.

Allen Childs  
Permittee/Operator representative  
[Signature]  
Signature

Environmental Engineer  
Title

Harold G. Sandbeck  
Division of Oil, Gas & Mining representative  
[Signature]  
Signature

Reclamation Inspector  
Title  
#27  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2723



NOTICE OF VIOLATION NO. N 89-27-9-1

Violation No. 1 of 1

Nature of violation

Failure to comply with the approved plan.

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

SAE 4 and SAE 7 as described in the plan on pages 7-72 and 7-72 b.

Remedial action required (including any interim steps)

- 1) Place treatment control measures along the <sup>top</sup> of the outslope at SAE 4 by August 14, 1989.
- 2) Comply with the approved plan or submit a revision

Abatement time (including interim steps)

September 8, 1989 at 5:00pm