



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gch

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: Complete: XXX Exploration:
Inspection Date & Time: 9/11/96 / 8:30a.m.-1:00p.m.
Date of Last Inspection: 8/21/96

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1210, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Gray
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Raining
Existing Acreage: Permitted- 2165.42 Disturbed- 5.55 Regraded- .5 Seeded- .5 Bonded- 5.55
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 listing various permit conditions and their evaluation status.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 9/11/96

(Comments are Numbered to Correspond with Topics Listed Above)

**1. PERMIT -**

- a) The permit was signed by the permittee and Division Director in June of 1994. The bonding amount is at \$703,000.
- b) The sediment pond inspection was completed for third quarter with no hazardous conditions existing. This inspection was taken on June 7, 1996.
- c) The Air Quality permit was issued on January 16, 1996 with increased tonnage due to longwall mining.
- d) The NPDES permit was issued on September 1, 1995 and expires on August 31, 2000. The water samples taken for first and second quarter discharges were in compliance with the permit.
- e) The water sampling of ground water, springs, and wells were taken for second quarter with more parameters taken than required by the permit.

**4A. DIVERSIONS -**

The diversions were spot-checked and were performing as designed. These diversions did contain water.

**4B. SEDIMENT POND -**

The sediment pond contained water but was not discharging during the inspection. The pond showed no signs of hazardous conditions. This pond was surveyed for sediment level and the conclusion is that it will be cleaned out in the fall of 1996.


**17. OTHER FACILITIES -**

The Forest Service road turn-around had no mine related vehicles within the area.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Genwal Resources, Inc. Marcia Petta (OSM)  
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office  
Date: September 19, 1996

Inspector's Signature:  #39  
Stephen J. Demczak