



NO. N98-39-6-1

notice of violation

To the following Permittee or Operator:

Name Genual Resources, Inc.

Mine Grandall Canyon Mine Surface Underground Other

County Emery State Utah Telephone 435-687-9813

Mailing Address PO Box 1420, Huntington, UT 84528

State Permit No. ACT/015/032

Ownership Category State Federal Fee Mixed

Date of inspection November, 19

Time of inspection 8:00 a.m. p.m. to 12:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., Utah Code Annotated, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Nov 24, 1998 Time of service/ mailing 3:00 a.m. p.m.

Gary Gray Permittee/Operator representative Title Mining Engineer

Mailed from DOGM Price Office
Signature

Stephen J Demczak Division of Oil, Gas & Mining representative Title Reclamation Specialist

Stephen J Demczak Signature Identification Number #39

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 98-39-6-1

Violation No. 1 of 1

Nature of violation

Failure to have some 3rd quarter water monitoring sample analyzed within the required holding times for some parameters.

Provisions of act, regulations or permit violated

R645-300-143
R645-301-723

Portion of operation to which notice applies

3rd quarter Water Monitoring samples for sulfates.

Remedial action required (including any interim steps)

None

Abatement time (including interim steps)

No Abatement.