

0023



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

INSPECTION REPORT

Handwritten initials/signature: PGL by [signature]

Partial: XXX Complete: Exploration:
Inspection Date & Time: 11/13/2001 / 9:30 - 12:00
Date of Last Inspection: 10/26/2001

Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1420, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Gray
State Official(s): Karl R. Houskeeper Federal Official(s): None
Weather Conditions: Overcast, Misting rain, Temp. 30-40's
Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, DISPOSAL OF EXCESS SPOIL, COAL MINE WASTE, PROTECTION OF FISH, SLIDES AND OTHER DAMAGE, CONTEMPORANEOUS RECLAMATION, BACKFILLING AND GRADING, REVEGETATION, SUBSIDENCE CONTROL, CESSATION OF OPERATIONS, ROADS, OTHER TRANSPORTATION FACILITIES, SUPPORT FACILITIES, AVS CHECK, AIR QUALITY PERMIT, BONDING & INSURANCE.

INSPECTION REPORT
(Continuation sheet)


PERMIT NUMBER: C/015/032

DATE OF INSPECTION: 11/13/2001

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

A small amount of coal was noted along side of the access road. The area has containment structures in place (silt fences) to treat any runoff from this area. The operator made note of the material and will have it removed.

Inspector's Signature: _____



Karl R. Houskeeper #49

Date: November 13, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Gary Gray, Genwal
Price Field office
O:\015032.CRA\Compliance\2001\p_1113.wpd