

INSPECTION REPORT

Partial XXX Complete Exploration
 Inspection Date: 06/17/2003/ Time: 9:30 – 11:30
 Date of Last Inspection: 05/13/2003

Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032
 Permittee and/or Operator's Name: Genwal Resources, Inc.
 Business Address: P.O. Box 1077, Price, Utah 84501
 Company Official(s): Gary Gray
 State Official(s): Karl R. Houskeeper Federal Official(s): None
 Weather Conditions: Clear, Temp 75°F
 Type of Mining Activity: Underground XXX Surface Prep Plant Other
 Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/032

DATE OF INSPECTION: 06/17/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Final approval for AM02A-2 was issued on April 15, 2003 for the South Crandall Portal construction. This amendment required the bond to be increased from \$1,654,000 to \$1,953,000.

Final approval for AM03A was issued on June 16, 2003 for Bond Adjustment. This amendment showed that the existing bond of \$1,654,000 is adequate for reclamation, including the new construction with the South Crandall Portals.

Construction for the new South Crandall Portals is scheduled to begin the week of June 23rd – 27th, 2003.

2. SIGNS AND MARKERS

The identification sign is located at the entrance to the permit area from the Forest Service road and contained the necessary information. The stream buffer zone sign located by the mine ID sign was lying on the ground. The operator re-installed the sign. All other markers observed during the inspection met the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The water level in the sediment pond has subsided. The level has dropped because inflow to the pond during the last month has decreased. The sediment pond is scheduled for cleaning this year.

4D. HYDROLOGIC BALANCE: WATER MONITORING

A review of the EDI website was done before the inspection. First quarter 2003 water monitoring information was not present in the EDI website during the review. The information was entered into the EDI website after the inspection. The information is being reviewed before notification to upload the information is given.

Inspector's Signature: _____ Date: June 18, 2003
Karl R. Houskeeper #49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Gary Gray, Genwal, via email
Price Field office

O:\015032.CRA\Compliance\2003\p_0617.doc