

0008

From: Karl Houskeeper
To: dshaver@coalsource.com
CC: Angela Nance; Daron Haddock; Suzanne Steab
Date: 4/6/2009 2:28 PM
Subject: March 2009 Inspection Reports
Attachments: Centennial March 2009.pdf; Crandall March 2009.pdf

Outgoing
COB10019
CO150032
X

Dave,

Attached are the March 2009 inspection reports for Centennial and Crandall.

Thanks,
Karl



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Inspection Report

Table with permit details: Permit Number: C0070019, Inspection Type: PARTIAL, Inspection Date: Wednesday, March 04, 2009, Start Date/Time: 3/4/2009 8:30:00 AM, End Date/Time: 3/4/2009 11:00:00 AM, Last Inspection: Wednesday, February 04, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 37 deg. F.

Inspection ID Report Number: 1936

Accepted by: jhelfric

3/11/2009

Table: Representatives Present During the Inspection. Columns: Company, Name, Title. Rows: David Shaver (Manager), April Abate (Hydrologist), Karl Houskeeper (Environmental Scientist III)

Permittee: ANDALEX RESOURCES INC TOWER DIVISION
Operator: ANDALEX RESOURCES INC TOWER DIVISION
Site: CENTENNIAL MINE
Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Acreage, Category. Rows: 6,516.91 Total Permitted, 47.19 Total Disturbed, Phase I, Phase II, Phase III

Mineral Ownership

- Checked: Federal, State, Fee
Unchecked: County, Other

Types of Operations

- Checked: Underground
Unchecked: Surface, Loadout, Processing, Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

Inspector's Signature:

Handwritten signature of Karl Houskeeper

Date: Wednesday, March 04, 2009

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1. Permits, Change, Transfer, Renewal, Sale

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.a Hydrologic Balance: Diversions

Most of the diversions are still snow covered or have snow within their reaches.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The bottoms of the sediment ponds have ice and/or snow in them.

8. Noncoal Waste

Noncoal waste items present on pad adjacent to the bathhouse. The noncoal waste consists of insulation that came off the bottom of a portable trailer unit that was removed from the site and transferred to Lila Canyon.



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:	
Company	David Shaver Manager
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Thursday, March 05, 2009
Start Date/Time:	3/5/2009 12:30:00 PM
End Date/Time:	3/5/2009 3:30:00 PM
Last Inspection:	Thursday, February 05, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 44 Deg. F.

InspectionID Report Number: 1938

Accepted by: jheltric

3/11/2009

Permittee: **GENWAL RESOURCES INC**
 Operator: **GENWAL RESOURCES INC**
 Site: **CRANDALL CANYON MINE**
 Address: **PO BOX 1077, PRICE UT 84501**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

6,235.80	Total Permitted
27.15	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: _____

Date

Thursday, March 05, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

All of the diversions are snow covered. The majority of the mine site is still snow covered, except for the plowed road access.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Dave Shaver indicated that the sediment pond is still being pumped. The water elevation was at the bottom of the oil skimmer.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2008 water monitoring is in the EDI website , but has not been uploaded by the Division. Water monitoring is current.