



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150032
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, August 27, 2013
Start Date/Time:	8/27/2013 8:00:00 AM
End Date/Time:	8/27/2013 2:00:00 PM
Last Inspection:	Tuesday, July 30, 2013

Representatives Present During the Inspection:
OGM Karl Houskeeper

Inspector: Karl Houskeeper

Weather: Overcast/Raining, Temp. 68 Deg. F.

InspectionID Report Number: 3593

Accepted by: jhelfric

8/28/2013

Permitee: **GENWAL RESOURCES INC**
 Operator: **GENWAL RESOURCES INC**
 Site: **CRANDALL CANYON MINE**
 Address: **PO BOX 910, EAST CARBON UT 84520-0910**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

6,295.06	Total Permitted
34.47	Total Disturbed
11.89	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the Main Office located at the West Ridge Mine. JD Leonard and Jay Marshall were not available. Completed the records review at West Ridge then proceeded to the Crandall Canyon Mine un-attended.

Water Samples of Pre 002 and 002 were taken. Photos were taken and are attached to the PDF version of this report.

REQUIRED ACTION ITEMS NEEDING ATTENTION!

- ITEM 4a
- ITEM 16a

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Tuesday, August 27, 2013



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit is effective 05/13/2013 and expires 05/13/2018. Other documents include the following:

- Certificate of Insurance issued 06/01/2013 and terminates 06/01/2014.
- Reclamation agreement is dated April 1998 and is signed by both parties.
- UPDES permit UT000024368 effective 05/01/2011 and expires midnight 04/30/2016.
- Air Quality permit DAQE-AN0225003-03, issued 03/20/2003.
- SPCC Plan dated 11/02/2009.

2. Signs and Markers

The mine identifications signs were observed at the main site for Crandall and at the Burma Pond. Both signs contained the required information and are in compliance with the R645 Utah Coal Rules.

4.a Hydrologic Balance: Diversions

The culvert inlet located adjacent to the iron treatment building has material built up on the trash rack and displaced at the base. The inlet needs to be cleaned, but remains functional.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first quarter 2013 pond inspection was done on 03/27/2013. Second quarter pond inspection was done on 06/03/2013. The pond has been cleaned. The clay liner has been augmented. Pond contains water from recent rain fall events.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for January 2013 through June 2013. Outfall 001 did not discharge during this time frame. Outfall 002 discharged for each of the referenced months but did not exceed any parameters.



Mine Water Treatment Highwall



Mine Water Treatment Highwall



Ditch DD-10



Mine Water Treatment Basin Outlet




Mine Water Treatment Basin (Looking West)



Mine Water Treatment Basin (Looking West)



Hilfiker/Road Slope Failure




Hilfiker/Road Slope Failure




Hilfiker/Road Slope Failure



Sediment Pond



Crandall Creek




Crandall Creek @ Pond Discharge




Sediment Pond



Sediment Pond



Hilfiker/Road Slope Failure



Hilfiker/Road Slope Failure



Diversion by Iron Treatment needs maintenance



Mine Site Overview



Iron Treatment Monitoring Screen



Burma Pond