AE 5-3-88 0010

File SUL

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 7, 1988
10:45 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P.O. Box P Salina, Utah 84654
Mine Name: Convulsion Canyon Permit Number: ACT/041/002
Type of Mining Activity: Underground X Surface ____ Other ____
County: Sevier State Utah
Company Official (s): Chris Kravits, Mike Davis
State Official(s): Daron Haddock
Partial: X Complete: ____ Date of Last Inspection: March 17, 1988
Weather Conditions: Clear, Sunny, Warm
Acreage: Permitted 7355 Disturbed 17 Regraded ____ Seeded ____ Bonded 27.9
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	( )	( )	(X)
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	(X)	( )	( )	(X)
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/041/002 DATE OF INSPECTION APRIL 7, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

A waste rock disposal site is still in the permitting process. A Technical Deficiencies Review completed by DOGM, was sent to SUFCO on March 30, 1988, wherein additional information was requested.

The Utah Department of Health has approved the site as of April 1, 1988 letter with 10 conditions attached.

3. Topsoil:

In regard to TDN N88-02-006-001 part 2, a submittal was made to DOGM on March 29, 1988 reflecting the current topsoil storage status. Upon request of DOGM, the operator also plans to submit a revised map indicating the location of the topsoil storage pile.

4b. Diversions:

Some of the drop drains around the yard need to be cleaned. Although there is no problem with drainage control they are part of the mine plan and should be maintained. Mr. Davis indicated that they would be cleaned as part of spring maintenance.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

(See #1 above) Waste rock is temporarily being stored at the mine site near the trash pit area until such time as the waste rock disposal site is permitted. I asked Mr. Davis (via a phone call on April 11) to notify the division in writing of this temporary storage condition.

14. Subsidence Control:

A subsidence report was submitted to DOGM on March 29, 1988 along with the annual report. The report was prepared by Engineer Dall Dimick using photogrammetric methods.

Copy of this Report:
Mailed to: Mike Davis (SUFCO)
Mailed to: SLC for Brian Smith (OSM), Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: April 12, 1988