

0017



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

APR 24
John

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 14, 1990
12:30pm - 3:45pm

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P.O. Box P, Salina, Utah 84654
Mine Name: Convulsion Canyon Mine Permit Number: ACT/041/002
Type of Mining Activity: Underground XX Surface Other
County: Sevier
Company Official (s): Mike Davis
State Official(s): Lynn Kunzler
Partial: Complete: X Date of Last Inspection: October 16, 1990
Weather Conditions: Cold and partly cloudy
Acreage: Permitted 7395 Disturbed 24.3 Regraded .5 Seeded .5 Bonded 67.8
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	(X)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION: Nov. 14, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

2. Topsoil:

Topsoil piles at the waste rock disposal area have been stabilized by seeding and mulching. Identification signs were in place.

4e. Surface and Ground Water Monitoring:

Water monitoring records were checked for the previous reporting period. All monitoring as required by the permit had been completed. NPDES reports were also checked and found to be in order.

6. Disposal of Development Waste and Spoil:

The waste rock disposal area was found to be in order with all diversions and ponds being well maintained. The first cell of the disposal area has been completed.

13. Revegetation:

The operator has completed revegetation of the first cell of the waste rock disposal area. This was completed during the last week of October, 1990. Seed materials were sampled by the Utah Dept. of Agriculture. The operator was requested to submit a copy of the report upon receipt. The operator has also seeded and mulched small areas throughout the disturbed area (for temporary stabilization) where past revegetation efforts were not as successful as desired.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Mike Davis - SUFCo, PFO

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number:  #17 Date: 12/5/90