

7049

0018



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

geh

NRZ

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: December 7, 1990
7:45am - 10:45am

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P.O. Box P, Salina, Utah 84654
Mine Name: Convulsion Canyon Mine Permit Number: ACT/041/002
Type of Mining Activity: Underground XX Surface Other
County: Sevier County
Company Official (s): Kris Kravits
State Official(s): Lynn Kunzler
Partial: X Complete: Date of Last Inspection: November 16, 1990
Weather Conditions: Cold and partly cloudy
Acreage: Permitted 17301 Disturbed 24.3 Regraded .5 Seeded .5 Bonded 67.8
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION: Dec. 07, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4d. Other Sediment Control Measures:

All diversion ditches, culverts and drop drains were inspected for blockage and maintenance and were found to be in working order.

4e. Surface and Ground Water Monitoring:

Water monitoring records were checked for the third quarter. All monitoring as required by the permit had been completed. NPDES reports indicated exceedences of the monthly average for TDS for 5 of 6 reporting periods. The Division had been notified by the State Health Dept. of the Violation and the Division subsequently issued a Violation to Sufco. The abatement for this violation is still outstanding (but not overdue).

6. Disposal of Development Waste and Spoil:

The waste rock disposal area was found to be in order with all diversions and ponds being well maintained. The first cell of the disposal area has been completed.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Mike Davis - SUFCO, PFO

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number:  #17 Date: 12/17/90