



NO. N 90-28-1-1

notice of violation

To the following Permittee or Operator:

Name Southern Utah Fuel Company

Mine Convulsion Canyon Surface Underground Other

County Sevier State Utah Telephone 637-4880

Mailing Address 397 So. 800 W. Salina Utah 84654

State Permit No. ACT/042/002

Ownership Category State Federal Fee Mixed

Date of inspection March 19, 1990, 19

Time of inspection 10:45 a.m. p.m. to 1:15 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing March 19, 1990 Time of service/ mailing 1:15 a.m. p.m.

Mike Davis Construction Engineer
Permittee/Operator representative Title

Mike Davis
Signature

Daron Haddock Permit Supervisor
Division of Oil, Gas & Mining representative Title

Daron R. Haddock
Signature

#28
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 90-28-1-1

Violation No. 1 of 1

Nature of violation

Failure to maintain sediment control structures
in a manner which prevents additional contributions
of sediment to stream flow outside the permit area,

Provisions of act, regulations or permit violated

UMC 817.45
UMC 817.42 a(1)
UMC 817.43(c)

Portion of operation to which notice applies

Silt fences at Waste Rock disposal site
ie. silt fence in Grass lined channel
and silt fence above Subsoil storage area,

Remedial action required (including any interim steps)

Repair or reinstall silt fences or other
treatment in diversions so that drainage
is treated prior to leaving permit area.

Abatement time (including interim steps)

April 9, 1990 1 PM.