

0042



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor  
Kathleen Clarke  
Executive Director  
Lowell P. Braxton  
Division Director

1594 West North Temple, Suite 1210  
PO Box 145801  
Salt Lake City, Utah 84114-5801  
801-538-5340  
801-359-3940 (Fax)  
801-538-7223 (TDD)

## INSPECTION REPORT

*PG 2 by [signature]*

Partial: XXX Complete: \_\_\_\_\_ Exploration: \_\_\_\_\_  
Inspection Date & Time: 10/24/2000 10:00am-3:00pm  
Date of Last Inspection: 10/24/2000

Mine Name: SUFECO Mine County: Sevier Permit Number: [redacted]  
Permittee and/or Operator's Name: Canyon Fuel Company  
Business Address: 397 South 800 West, Salina, Utah 84564  
Type of Mining Activity: Underground XXX Surface \_\_\_\_\_ Prep. Plant \_\_\_\_\_ Other \_\_\_\_\_  
Company Official(s): Glen Lewis  
State Official(s): Stephen J. Demczak Federal Official(s): None  
Weather Conditions: Clear, 40's, 2 inches snow cover  
Existing Acreage: Permitted 17621.29 Disturbed 70.189 Regraded \_\_\_\_\_ Seeded \_\_\_\_\_  
Status: Active XXX

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	<u>EVALUATED</u>	<u>N/A</u>	<u>COMMENTS</u>	<u>NOV/ENF</u>
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: 11/29/2000

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

Several diversions were spot-checked throughout the SUFCO property. The diversions were functioning as designed. No problems were noted.

**4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS**

The mine site sediment pond was inspected with no hazardous conditions being noticed. The pond did contain water and was discharging.

**4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES**

The permittee uses silt fences as the main treatment for alternate sediment control areas. The silt fences were functioning as designed and were treating the water.

**7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS**


The refuse pile was inspected and no hazardous conditions were noted.

**8. NONCOAL WASTE**

Non-coal waste in the disturbed area has started to accumulate. The permittee has been advised about the concern and has committed to take action.

**18. SUPPORT FACILITIES/UTILITY INSTALLATIONS**

No construction was occurring at the SUFCO mine.

Inspector's Signature:   
Stephen J. Demczak #39

Date: December 5, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM  
Ken May, Canyon Fuel  
Price Field office

O:\041002.CON\Compliance\2000\p\_1129.wpd