



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah Monitoring

Vicky Miller <vmiller@bowieresources.com>

Mon, Nov 3, 2014 at 10:15 PM

To: "Steve Christensen (stevechristensen@utah.gov)" <stevechristensen@utah.gov>, "Amanda Daniels (amandadaniels@utah.gov)" <amandadaniels@utah.gov>, "OGMCOAL OGMCOAL (OGMCOAL@utah.gov)" <OGMCOAL@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>

Cc: John Byars <jbyars@bowieresources.com>, Wyatt Shakespear <WShakespear@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

Attached is a map showing the location of mining on November 2, 2014.

The South Fork was monitored on October 20, 23, 27 and 31st.

On the dates listed above the channel became dry approximately 100 meters above where the culvert crosses the road to just below monitoring location 006C (4742, 4812). The flow was estimated to be 5 to 8 gpm at the location below 006C and the channel continued to gain flow until it joined with the flow for the Wedge and Amanda Springs. The springs along the South Fork were all flowing during the two week monitoring period (4714, 4719, 4806).

No new cracks were located during this monitoring period and no notable precipitation has fallen in the last four weeks.

Slow moving water above monitoring location 006 was observed to be covered with ice, during the monitoring on the 27th and 31st (4795). The ponds were dry and no livestock was observed in the area.

7 attachments

IMG4714.JPG
1895K



IMGP4719.JPG
1902K



IMGP4742.JPG
1838K



IMGP4795.JPG
1941K



IMGP4812.JPG
1851K



IMGP4806.JPG
1918K



Nov 2 Mining.PDF
40K