State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0410002**
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, January 13, 2016
Start Date/Time:	1/13/2016 8:00:00 AM
End Date/Time:	1/13/2016 2:20:00 PM
Last Inspection:	Thursday, December 01, 2016

Representatives Present During the Inspection:	
Company	Vicky Miller
OGM	Karl Houskeeper

Inspector: Karl Houskeeper,

Weather: Clear Skies, Temp. 24 Deg. F.

InspectionID Report Number: 5405

Accepted by: JHELFRIC
1/14/2016

Permitee: **CANYON FUEL COMPANY**
Operator: **CANYON FUEL COMPANY**
Site: **SUFCO MINE**
Address: **597 SOUTH SR24, SALINA UT 84654**
County: **SEVIER**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

720.48	**Total Permitted**
49.66	**Total Disturbed**
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [x] State
- [ ] County
- [ ] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Wednesday, January 13, 2016

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

Permit Number: C0410002
Inspection Type: PARTIAL
Inspection Date: Wednesday, January 13, 2016

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2.	Signs and Markers	☑	☐	☑	☐
3.	Topsoil	☐	☐	☐	☐
4.a	Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c	Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d	Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e	Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5.	Explosives	☐	☐	☐	☐
6.	Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7.	Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8.	Noncoal Waste	☐	☐	☐	☐
9.	Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10.	Slides and Other Damage	☐	☐	☐	☐
11.	Contemporaneous Reclamation	☐	☐	☐	☐
12.	Backfilling And Grading	☐	☐	☐	☐
13.	Revegetation	☐	☐	☐	☐
14.	Subsidence Control	☐	☐	☐	☐
15.	Cessation of Operations	☐	☐	☐	☐
16.a	Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b	Roads: Drainage Controls	☐	☐	☐	☐
17.	Other Transportation Facilities	☐	☐	☐	☐
18.	Support Facilities, Utility Installations	☐	☐	☐	☐
19.	AVS Check	☐	☐	☐	☐
20.	Air Quality Permit	☐	☐	☐	☐
21.	Bonding and Insurance	☐	☐	☐	☐
22.	Other	☐	☐	☐	☐

2. Signs and Markers

Observed the mine identification signs at the septic field, pump house main sediment pond, main facilities, waste rock site and waste rock site expansion. All signs were found to be compliant.

4.a Hydrologic Balance: Diversions

Diversions throughout the mining permit area are all snow covered.

7. Coal Mine Waste, Refuse Piles, Impoundments

Construction work on the waste rock expansion site was occurring during the partial inspection. Work on rip rap placement and road construction were the current area of focus.

The existing waste rock site appeared stable. No visible hazards were observed.