0012 ✓ KY 3-18-87

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

jdh 1-18-87

inspection report

Permit No. INA/043/001

Inspection Date 2/24/87

Permittee/Operator Name SUMMIT MINERALS, INC.

Business Address 221 WEST 2100 SOUTH

City SALT LAKE CITY State UTAH Zip 84115

Mine SUMMIT MINERALS #1 ☐ Surface ☒ Underground ☐ Other

County SUMMIT State UTAH

Company Official(s) DALE WRIGHT

State Official(s) DAVID LOF ACCOMPANIED BY HENRY AUSTIN - OSM

Time of inspection 11:30 ☒ a.m. ☐ p.m. to 12:05 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 1/15/87 Weather conditions MOSTLY CLOUDY & COLD

Acreage — ☐ Permitted 16 ☐ Disturbed — ☐ Regraded — ☐ Seeded 16 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☒	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. FNA/043/001

Inspection Date 2/24/87

Please number comments to correspond with topics on previous page.

1) PERMITS

THE OPERATOR IS STILL IN COMPLIANCE WITH THE BOARD OF OIL, GAS & MINING'S ORDER DATED DECEMBER 1985 AND IS PROCEEDING WITH PERMITTING OF THEIR RECLAMATION PLAN. ON 1/23/87 THE DIVISION MADE A DETERMINATION OF COMPLETENESS WITH REGARDS TO THE RECLAMATION PLAN. SINCE THAT TIME THE DIVISION HAS REVIEWED THE COMPLETE PLAN FOR TECHNICAL ADEQUACY. ON 3/12/87 THE DIVISION SENT THE OPERATOR A TECHNICAL DEFICIENCY LETTER DETAILING TECHNICAL DEFICIENCIES THAT WERE FOUND IN THE PLAN.

GENERAL FIELD INSPECTION COMMENTS

AT THE TIME OF INSPECTION THERE WERE 6-12" OF SNOW AT THE MINESITE. NO ~~ADDITIONAL~~ ACTIVITY HAS OCCURRED AT THE MINESITE SINCE MY 1/15/87 INSPECTION OTHER THAN SNOW REMOVAL ON THE ROAD. THE OPERATOR HAS INSTALLED STRAWBALES AT SEVERAL POINTS ALONG THE ROAD INORDER TO CONTROL AND TREAT SNOW MELT RUNOFF ALONG THE ROAD. THERE WAS NO RUNOFF OCCURRING AT THE TIME OF THE INSPECTION. IT APPEARED THAT MOST OF THE DISTURBED AREA RUNOFF FROM THE SITE WILL BE CONTAINED IN TWO EXISTING IMPOUNDMENTS. RUNOFF NOT GOING TO THE IMPOUNDMENTS WILL PASS THROUGH THE STRAWBALES MENTIONED ABOVE. SNOW COVER OVER THE REST OF THE SITE PRECLUDED A THOROUGH SITE INSPECTION.

Copy of report mailed to DONNA GRIFFIN-OSM BARBARA FILAS - SUMMIT MINERALS

Copy of report given to JOE HELFRICH & SUE LINNER - DOGM

Inspector's signature David Lof 3/17/87 No. #4

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE