

0002



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

APR 74  
JOK

## INSPECTION REPORT

INSPECTION DATE & TIME: June 6, 1990

Noon to 1:00 pm

Permittee and/or Operators Name: Summit Minerals, Inc.  
 Business Address: 221 West 2100 South, Salt Lake City, Utah 84115  
 Mine Name: Summit Minerals #1 Permit Number: INA/043/001  
 Type of Mining Activity: Underground  Surface  Other   
 County: Summit  
 Company Official (s): None  
 State Official(s): Harold G. Sandbeck  
 Partial:  Complete:  Date of Last Inspection: 3/2/90  
 Weather Conditions: Clear and warm  
 Acreage: Permitted 0 Disturbed 16 Regraded  Seeded  Bonded 16  
 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	(XX )	( )	(XX )
2. SIGNS AND MARKERS	(XX )	( )	( )	( )
3. TOPSOIL	( )	( )	(XX )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	(XX )	( )
b. DIVERSIONS	(XX )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(XX )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(XX )	( )	( )	( )
f. EFFLUENT LIMITATIONS	(XX )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(XX )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	(XX )	( )
7. COAL PROCESSING WASTE	( )	( )	(XX )	( )
8. NONCOAL WASTE	(XX )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(XX )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(XX )	( )
12. BACKFILLING AND GRADING	( )	( )	(XX )	( )
13. REVEGETATION	( )	( )	(XX )	( )
14. SUBSIDENCE CONTROL	( )	( )	(XX )	( )
15. CESSATION OF OPERATIONS	( )	( )	(XX )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(XX )	( )
b. DRAINAGE CONTROLS	(XX )	( )	( )	( )
c. SURFACING	(XX )	( )	( )	( )
d. MAINTENANCE	(XX )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(XX )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(XX )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION 6/6/90


(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits. Summit Minerals has been denied a permit. Forfeiture of the reclamation bond is currently ongoing and the reader is referred to the Division correspondence files for additional information. No evidence of mining or mining related activities were noted.

Copy of this Report:

Mailed to: Jack Higgins(Summit Minerals), Price Office & Brian Smith(OSM

Given to: Darron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number:  #27 Date: 6/8/90