



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

get
10/27

INSPECTION REPORT

INSPECTION DATE & TIME: December 4, 1991
1:00 P. M. - 2:00 P. M.

Permittee and/or Operator's Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, UT 84115
Phone: (801) 486-1861

County: Summit

Mine Name: Summit #1 Permit Number: INA/043/001 Type of
Mining Activity: Underground Surface Other

Company Official(s): None

State Officials(s): Priscilla Burton, Wayne Western

Federal Official(s): None

Partial: Complete Date of last Inspection: 11/27/91

Weather Conditions: Sunshine, 4" snow on ground, 40's

Acres: Permitted 0 Disturbed 16 Regraded

Seeded Bonded 16 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	(X)	()
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	(X)	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	()	()	(X)	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	(X)	()
b. DRAINAGE CONTROLS	()	(X)	()	()
c. SURFACING	()	()	(X)	()
d. MAINTENANCE	()	()	(X)	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION: 12/4/91

(Comments are Numbered to Correspond with Topics Listed Above)

No changes have occurred at this site since the last complete inspection. All slopes remain stable. Ponds are empty of water. There is evidence (tire tracks) of people driving into the site, using the eastern perimeter road (to the old gravel pit).

1. PERMITS

The Division is being advised by the Division of State Lands and Forestry concerning the sale of the Wallsburg property (posted as collateral bond).

Copy of this Report:

Mailed to: Brian Smith(OSM); Jack Higgins (Summit)

Given to: Daron Haddock, DOGM; Joe Helfrich, DOGM

Inspector's Signature & Number:

Dwaine Banton

#37

Date: 12/4/91