

0002



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

10027
Jed

INSPECTION REPORT

INSPECTION DATE & TIME: November 27, 1991
1:30 P. M. - 2:30 P. M.

Permittee and/or Operator's Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, UT 84115
Phone: (801) 486-1861
Mine Name: Summit #1 Permit Number: INA/043/001
Type of Mining Activity: Underground X Surface Other
County: Summit Company Official(s): None Present
State Officials(s): Randy Harden
Federal Official(s): None
Partial: X Complete Date of last Inspection: 10/31/91
Weather Conditions: Partly cloudy, muddy, 30's
Acreage: Permitted 0 Disturbed 16 Regraded
Seeded Bonded 16 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION: 11/27/91

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

The access gate to the mine site was closed and posted. There was no sign of any activity at the site. Essentially all conditions at the site are the same as reported during previous inspections.

1. PERMITS

Recent correspondence with the Division of State Lands and Forestry has indicated the potential for sale of the property being held as bond for the operations. Information provided in that correspondence indicates that the value of the property is significantly less than the amount required to conduct reclamation.


18. SUPPORT FACILITIES / UTILITY INSTALLATIONS

The buildings located on the site are not in use for mining operations or by the landowner. No evidence of any activity on the site is apparent except for use of the road through the site for access to adjacent properties.

Copy of this Report:

Mailed to: Brian Smith(OSM); Jack Higgins (Summit)

Given to: Daron Haddock, DOGM; Joe Helfrich, DOGM

Inspector's Signature & Number:  #13

Date: January 8, 1991