



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gh

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 31, 1991
4:00 to 4:30 pm

Permittee and/or Operators Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, Utah 84115
Mine Name: Summit #1 Permit Number: INA/043/001
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official(s): None
State Official(s): Daron R. Haddock
Partial: Complete: Date of Last Inspection: Sept. 11, 1991
Weather Conditions: slightly overcast, cold
Acreage: Permitted 0 Disturbed 16 Regraded Seeded Bonded 16
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	(X)
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	()	(X)	()	(X)
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/001

DATE OF INSPECTION: October 31, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The site remains abandoned. No sign of recent activity is apparent at the site. Approximately 3-4 inches of snow cover the site.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The impounding structures appear to be intact and functioning. Although lacking maintenance, there does not appear to be problems with the erosion and sediment control measures on site.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES:

The site is heavily used by wildlife as evidenced by the tracks in the snow. Both deer and cottontail rabbits were observed.

16a. ROAD CONSTRUCTION:

The bridge going over Chalk Creek is in questionable condition. Although not considered dangerous it is doubtful whether large equipment could utilize the bridge. Access to the site is limited, due to the gate being closed and the site being posted "No Trespassing".

Copy of this Report:

Mailed to: Bernie Freeman (OSM), PFO

Given to: Joe Helfrich

Inspectors Signature & Number: Daron R. Haddock # 28 Date: November 1, 1991

-

Daron R. Haddock