

0009



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

*Handwritten initials/signature*

Michael O. Leavitt  
Governor  
Ted Stewart  
Executive Director  
James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

Partial: \_\_\_ Complete: X Exploration: \_\_\_  
Inspection Date & Time: May 25, 1993 5:00pm-6:00pm  
Date of Last Inspection: April 22, 1993

Mine Name: SUMMIT #1 County: SUMMIT Permit Number: INA/043/001

Permittee and/or Operator's Name: Summit Minerals, Inc.

Business Address: 221 W 2100 S, SLC UT 84115

Type of Mining Activity: Underground X Surface \_\_\_ Prep. Plant \_\_\_ Other \_\_\_

State Official(s): R. Harden

Company Official(s): None

Federal Official(s): None

Weather Conditions: Clear, Warm

Existing Acreage: Permitted-\_\_\_ Disturbed-16 Regraded-\_\_\_ Seeded-\_\_\_ Bonded-16

Increased/Decreased: Permitted-\_\_\_ Disturbed-\_\_\_ Regraded-\_\_\_ Seeded-\_\_\_ Bonded-\_\_\_

Status: \_\_\_ Exploration/\_\_\_ Active/\_\_\_ Inactive/\_\_\_ Temporary Cessation/ X Bond Forfeiture

Reclamation ( \_\_\_ Phase I/ \_\_\_ Phase II/ \_\_\_ Final Bond Release/ \_\_\_ Liability \_\_\_ Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION: May 25, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

### 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

No evidence of any mining or related activities since the time of the last inspection are apparent. No trespassing signs are posted and the gate to the site is closed.

Due to cloud cover and weather conditions, aerial photograph for the site was not taken until June 10, 1993. Manuscripts of the contour information are expected from the contractor by the end of June.

Reclamation activities for the Summit #1 site are not anticipated this year. No funds have been made available for reclamation through bond forfeiture due to the inability to convert the property held as collateral into monies for reclamation.

### 4. HYDROLOGIC BALANCE:

Neither pond on the site was holding water at the time of the inspection. No discharge from the ponds or any of the diversions were evident at the time of the inspection.

### 16. ROADS:

The bridge over Chalk Creek is in worsening condition due to the abnormally high spring runoff this year. The earth abutments on both sides of the bridge have been eroded into the river and the bridge is no longer passable to vehicles. Extreme caution should be used when attempting to cross the bridge on foot. Sever undercutting of the embankments has left highly unstable and steep slopes along and beneath the road and bridge structure. The remainder of the road to and through the site appears to be in good condition with little erosion evident.


### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

It appears that no equipment or activity has occurred at the site including any access to or through the site.

Copy of this Report:

Mailed to: Marcia Petta (OSM)

Given to: Joe Helfrich, Daron Haddock (DOGM)

Inspector's Signature: 

# 13 Date: June 28, 1993