

Document Information Form

Mine Number: C/043/008

File Name: Internal

To: DOGM

From:

Person N/A

Company SUMMIT COAL Co.

Date Sent: N/A

Explanation:

INSPECTION REPORT

cc:

File in: C/043/008, 1987, Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

11-16-87

File JOK

INSPECTION REPORT

INSPECTION DATE & TIME: October 29, 1987
8:15 a.m. to 10:30 a.m.

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 752, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/002
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): none
State Official(s): Rick Summers, Lynn Kunzler
Partial: Complete: Date of Last Inspection: 9/18/87
Weather Conditions: Clear
Acreage: Permitted 129 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | <u>YES</u> | <u>NO</u> | <u>N/A</u> | <u>COMMENTS</u> |
|--|------------|-----------|------------|-----------------|
| 1. PERMITS | (X) | () | () | (X) |
| 2. SIGNS AND MARKERS | () | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | () | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | () | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | (X) | () | () | (X) |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | (X) | () | () | (X) |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | (X) | () | () | (X) |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | () |
| 18. SUPPORT FACILITIES | () | () | () | () |
| UTILITY INSTALLATIONS | () | () | () | () |

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No 0005 Date 1/4
In C/ 043/002, 1987 Internal
For additional information

11-16-87

File Jd

INSPECTION REPORT

INSPECTION DATE & TIME: October 29, 1987
8:15 a.m. to 10:30 a.m.

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P.O. Box 752, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/002
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): none
State Official(s): Rick Summers, Lynn Kunzler
Partial: Complete: Date of Last Inspection: 9/18/87
Weather Conditions: Clear
Acreage: Permitted 129 Disturbed 10 Regraded Seeded Bonded 10
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | <u>YES</u> | <u>NO</u> | <u>N/A</u> | <u>COMMENTS</u> |
|---|------------|-----------|------------|-----------------|
| 1. PERMITS | (X) | () | () | (X) |
| 2. SIGNS AND MARKERS | () | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | () | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | () | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | (X) | () | () | (X) |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | (X) | () | () | (X) |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | (X) | () | () | (X) |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | (X) | () |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | () | () | (X) | () |

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/002

DATE OF INSPECTION October 29, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

The operator has submitted a response to the Division's review of the permit stipulation response package (received 9/24/87) which is currently under review. The operator submitted a request for an extension to respond to stipulations 817.71-1-JRH and UMC 800-(1)-JRH on October 27, 1987. Additional time is needed to determine an adequate solution for the disposal of waste rock at the site.

4e. Surface and Groundwater Monitoring

The continuous recorder for measurement of flows from WS-4 was inspected and found to be adequately located and installed. Discussions with onsite personnel indicated that no runoff had occurred within the previous month at the site.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

The operator was given an extension to 11/15/87 to install the wildlife protection fence. The extension was necessary due to questions concerning the location of the fence and the location of a potential waste rock disposal area. It was determined that the fence should be installed at this time. If additional fencing is required for the waste rock area the operator will be notified through the permitting process for that area.

13. Revegetation

Lynn Kunzler, Division Biologist, was present during this inspection to conduct sampling of vegetation reference area in order to verify the adequacy of the operator's recently submitted survey. The sampling data is currently being analyzed and this issue will be resolved through the permitting process. Please reference memo to technical file, Lynn Kunzler, dated November 5, 1987.

Copy of this Report:

Mailed to: John Kathmann, Jack Blonquist (Summit Coal Company)

Given to: NOV File, Sue Linner

Inspectors Signature and Number: Rick Summers #15 Date: 11/3/87