

2-24-89
7022

0025



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 89-27-1-2

notice of violation

To the following Permittee or Operator:

Name Summit Coal Company

Mine Boyer Mine Surface Underground Other

County Summit State Utah Telephone 336-5514

Mailing Address P.O. Box 646, Coalville, Utah 84017

State Permit No. ACT/043/008

Ownership Category State Federal Fee Mixed

Date of inspection February 16, 1989, 19 89

Time of inspection 10:00 a.m. p.m. to 1:00 a.m. p.m.

Operator Name (other than Permittee) Jack Blonquist

Mailing Address Same As Above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailing February 16, 1989 Time of service/mailing Noon a.m. p.m.

Jack Blonquist
Permittee/Operator representative

Mine Manager
Title

Jack Blonquist
Signature

Reclamation Spec.
Title

Harold G. Sandbeck
Division of Oil, Gas & Mining representative

#27
Identification Number

Harold G. Sandbeck
Signature

SEE REVERSE SIDE

WHITE-DOGMI YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2713



NOTICE OF VIOLATION NO. N 89-27-1-2

E

Violation No. 1 of 2

Nature of violation

Failed to submit the VO-1 culvert revisions and certifications as required by the permit.

Provisions of act, regulations or permit violated

VMC 771.19

Portion of operation to which notice applies

VO-1 bypass culvert.

Remedial action required (including any interim steps)

See field amendment ACT/043/008-88E.

Abatement time (including interim steps)

May 16, 1989 at 5:00 PM



NOTICE OF VIOLATION NO. N 89-27-1-2

G

Violation No. 2 of 2

Nature of violation

Failure to conduct water monitoring as per approved permit.
Failed to collect water samples for the months of November, December,
January and February.

Provisions of act, regulations or permit violated

VMC 771.19

Portion of operation to which notice applies

Boyer Mine Sampling Sites

Remedial action required (including any interim steps)

None

Abatement time (including interim steps)

No abatement possible. However, the operator is advised to follow the
requirements of his approved plan.