



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

0271  
Jch

## INSPECTION REPORT

INSPECTION DATE & TIME: December 4, 1991  
11:00am - 12:00 pm

Permittee and/or Operator's Name: Summit Coal Co.  
Business Address: P.O. Box 646, Coalville UT 84017  
County: Summit  
Mine Name: Boyer Mine Permit Number: INA/043/008  
Type of Mining Activity: Underground  Surface  Other   
Company Official(s): N/A  
State Officials(s): Priscilla Burton, Wayne Western  
Federal Official(s): none  
Partial:  Complete:  Date of last Inspection: 11/27/91  
Weather Conditions: sunshine, 4" snow on ground, 40's  
Acreage: Permitted=170 Disturbed=5.5 Regraded=0 Seeded=0  
Bonded=5.5 Enforcement Action: none

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	(X)
3. TOPSOIL	(X)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	(X)	( )	( )
b. DIVERSIONS	( )	(X)	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	(X)	( )
f. EFFLUENT LIMITATIONS	( )	( )	(X)	( )
5. EXPLOSIVES	(X)	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	(X)	( )	(X)
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	( )	(X)	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	(X)	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(X)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(X)	( )
12. BACKFILLING AND GRADING	(X)	( )	( )	(X)
13. REVEGETATION	( )	( )	(X)	( )
14. SUBSIDENCE CONTROL	( )	( )	(X)	( )
15. CESSATION OF OPERATIONS	( )	(X)	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	(X)	( )	( )
c. SURFACING	( )	( )	(X)	( )
d. MAINTENANCE	( )	( )	(X)	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(X)	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	(X)	( )

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008 DATE OF INSPECTION: December 4, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

### 1. PERMITS

The sale of the Park City property, held as a collateral form of bond for reclamation, is still pending.

### 2. SIGNS AND MARKERS

An AVS check of the sign was not confirmed by the information provided in the permit.

The sign lists the address for the Boyer Mine as P.O. Drawer 7; Coalville UT 84017. Telephone: 561-8902.

The permit lists the address as P.O. Box 646; Coalville UT. Telephone: 336-5514.

### 4. b. HYDROLOGIC BALANCE -- DIVERSIONS

Snow on the ground impaired our view of culvert inlets and outlets and of rills and gullies. However, the situation remains the same as described in the last complete inspection report.

### 6. DISPOSAL OF DEVELOPMENT WASTE

Development waste stored on the surface has begun sloughing in a new location. The material is creeping onto the weigh station pad.

### 12. BACKFILLING AND GRADING

The portals remain sealed.

Copy of this Report:

Mailed to:

Given to:

Brian Smith, Offic of Surface Mining

Joe Helfrich and Daron Haddock, DOGM

Inspector's Signature & Number: *Parla Cal Brunton* #37 Date: 12/4/91