

1-0003



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Jch

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 31, 1991
3:30 P.M. to 4:00 P.M.

Permittee and/or Operators Name: Summit Coal Co.
Business Address: P. O. Box 646 Coalville Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground XX Surface _____ Other _____
County: Summit
Company Official(s): None
State Official(s): Daron R. Haddock
Partial: XX Complete: _____ Date of Last Inspection: September 11, 1991
Weather Conditions: Slightly Overcast, Cold
Acreage: Permitted 170 Disturbed 5.5 Regraded _____ Seeded _____ Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	(X)	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	(X)
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	(X)	()	(X)
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION: Oct. 31, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The site remains abandoned. There are no new signs of activity since my last inspection of the site. Most of the site was covered with 3-4 inches of recent snow. There are no immediate threats to the health and safety of the public apparent at the site.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Although the site is inactive and abandoned, there appears to be fairly good sediment control. The sediment pond is in good condition and is catching most of the runoff from the site. There is plenty of storage capacity available.

6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL:

The coal refuse piles were inspected for burning. No fires were observed.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES:

The mine site appears to be a haven for wildlife. A red fox, deer, and eagle were all observed at the site.

16c. ROAD SURFACING:

The roads going through the site appear to be showing signs of erosion. This is partly due to the lack of drainage control as well as the lack of surfacing material on the roads.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), PFO

Given to: Joe Helfrich



Inspectors Signature & Number: Daron R. Haddock #28 Date: November 1, 1991