



0009

# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

007  
JL

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: 04/27/92  
12:30 - 1:15

Permittee and/or Operators Name: Summit Coal Co.  
Business Address: P.O. Box 646, Coalville UT 84017  
Mine Name: Boyer Mine Permit Number: INA/043/008  
Type of Mining Activity: Underground  Surface  Other   
County: Summit  
Company Official (s): None  
State Official(s): Sharon Falvey  
Partial:  Complete:  Date of Last Inspection: 3/18/92  
Weather Conditions: Windy, Partly cloudy  
Acreage: Permitted 170 Disturbed 5.5 Regraded 0 Seeded 0  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(x)	( )	( )	(x)
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	(x)	( )	( )	(x)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )
OTHER INFORMATION	( )	( )	( )	( )

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION: 4/27/92

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. DIVERSIONS

All drainages are functioning although the haul road at the south west corner of the site appears to a small amount of runoff which is leaving the disturbed area along the road. The road is graded at the corner toward the drainage within the disturbed area. The inslope needs to be increased or a wate bar installed. The berm adjacent to the road is functioning.

8. NONCOAL WASTE

Generators, Transformer, Disintegrated Batteries, a few pails and barrels with waste products, tarlike substance and miscellaneous containers are located at the site. Some containers are begining to show signs of corrosion. Barrels of unknown liquids are present. A "dry chemical" container is present, I assume the pressure was prevoiusly released from the container.

Copy of this Report:

Mailed to: Brian Smith (OSM)

Given to: Daron Haddock, Jim Smith, Joe Helfrich (DOGM)

Inspector's Signature: Shawn K Fahney #38 Date: 5/5/92 4/28/92