



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Jch

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: x Complete: Exploration:
Inspection Date & Time: February 18, 1994 / 16:00-16:30
Date of Last Inspection: January 19, 1994

Mine Name: Boyer Mine County: Summit Permit Number: INA /043/008
Permittee and/or Operator's Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Type of Mining Activity: Underground x Surface Prep. Plant Other
State Officials(s): Wayne Western
Company Official(s): None Federal Official(s): None
Weather Conditions: Snowing heavily and strong winds temp. 20's
Existing Acreage: Permitted- 170 Disturbed- 5.5 Regraded- 0 Seeded- 0 Bonded- 5.5
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ x Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION: February 18, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments:

The site was covered with 4" to 8" of snow. Approximately 1/2" of snow fell during the inspection. There were no tracks in the snow indicating that no one had been on the site since the last snow fell, 2-3 weeks ago. Many features were not visible due to the snow cover. Snow covered the coal mine waste piles indicating they were not on fire.

4a. DIVERSIONS

The diversions were all covered with snow. In the past, snow in the diversions has not resulted in major erosional problems. The new water bar and diversion ditch should minimize the erosion caused by the spring runoff.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS WASTE

A few years ago, there were some areas in the coal mine waste piles that would catch on fire. The piles are now covered with snow indicating that the hot spots have cooled off. The sign warning of coal mine fires is still visible.

There was 8" of snow in the bottom of the sediment pond. The exit to the decant pipe is free from snow and ice.

Copy of this Report:

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Wayne W. Turner #42 Date: 2/22/94

BOY0194.WHW