

0015



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: x Complete: Exploration:
Inspection Date & Time: January 19, 1994 / 14:00-15:00
Date of Last Inspection: December 13, 1993

Mine Name: Boyer Mine County: Summit Permit Number: INA /043/008
Permittee and/or Operator's Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Type of Mining Activity: Underground x Surface Prep. Plant Other
State Officials(s): Lucia Malin, Mark Mesch, Chris Roher & Wayne Western
Company Official(s): None Federal Official(s): None
Weather Conditions: Sunny and cool, snow covered most of the shady areas
Existing Acreage: Permitted- 170 Disturbed- 5.5 Regraded- 0 Seeded- 0 Bonded- 5.5
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ x Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

NOV/ENF

EVALUATED N/A COMMENTS

Table with 4 columns: NOV/ENF, EVALUATED, N/A, COMMENTS. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION: January 19, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments:

During the inspection I briefed the Abandoned Mines Lands staff on the reclamation plans. The mine is scheduled to be reclaimed this year. The Title V will provide the engineering support and Title IV will administer the contract. Reclamation work is scheduled to begin this spring and be completed by autumn.

4a. DIVERSIONS

The new waterbar has stabilized the erosion of the main mine road. Low precipitation, and cold temperatures have resulted in low runoff. Much of the snow has evaporated rather than melted and absorbed into the soil.

Copy of this Report:

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Wayne A. Jensen

#42 Date: 1/31/94

BOY0194.WHW