FORM MR-AR
(Revised 5/97)

RECEIVED
JAN 29 1998
DIV. OF OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. *General Information*

1. Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97
2. DOGM File Number (Mine No): S 1015 1040
3. Mine Name: ROCKLAND MINE
4. Mineral(s) Mined (or permitted to mine): HUMIC SHALE
5. Type of mine ☐ Surface Mine or ☑ Underground Mine
6. Legal Description (Location of Lands Affected):

Lot 2 1/4, ____ 1/4, ____ 1/4, Section 2, Township 23S, Range 6E
Lot 3 1/4, ____ 1/4, ____ 1/4, Section 2, Township 23S, Range 6E.
SW 1/4, NE 1/4, ____ 1/4, Section 2, Township 23S, Range 6E

7. Name of Operator or Company: MIRACLE ROCK MINING
8. Permanent Street Address: 400 So. 200E
   City, State, Zip: EMERY UTAH 84522
   Phone: 435-286-2222
9. Company Representative (or designated operator):
   Name: DAVID TAYLOR
   Title: PRES.
   Business Address: 400 S. 200E
   City, State, Zip: EMERY UTAH 84522
   Phone: 435-286-2222

☐ **Please check if any of the above information has changed since previous year.**

II. *Mining and Reclamation*

1. Was the mine active during the past year? Yes ☑ No ☐
2. If active, how much ore or mineral was mined? 6328 Tons
3. *If inactive*, what year was the mine **last active**? ____

3. How much **additional acreage** was disturbed during the past year? 1 ac.

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

SIDE HILL WAS FACED OFF FOR NEW PORTAL

5. How much acreage was **reclaimed** during the past year? 1 ac.

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

LOWER LANDING REGRADED AND RESEEDED

7. What is the **total disturbed acreage** at years end? 4 1/2 ac.

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

NOTE: Section III., "Additional Information" applies only to **large mining operations.**

III. *Additional Information*

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.

2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. *Signature Requirement*

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): DAVID TAYLOR

Title of Operator: PRES

Signature of Operator: David Taylor

Date: 1/27/98

jb
MR-AR