4e

FORM MR-AR
(Revised 5/97)

RECEIVED
DEC 19 1997
DIV. OF OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. *General Information*

1. Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97
2. DOGM File Number (Mine No): M/015/062
3. Mine Name: ECDC CLAY
4. Mineral(s) Mined (or permitted to mine): _____
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected): SEE ENCLOSED SHEET

   _____1/4, _____1/4, _____1/4, Section _____, Township _____, Range _____

   _____1/4, _____1/4, _____1/4, Section _____, Township _____, Range _____

   _____1/4, _____1/4, _____1/4, Section _____, Township _____, Range _____

7. Name of Operator or Company: ECDC ENVIRONMENTAL
8. Permanent Street Address: 1111 W HWY 123

   City, State, Zip: EAST CARBON, UT

   Phone: 801-888-4418
9. Company Representative (or designated operator):

   Name: DARIN OLSON

   Title: FACILITY ENGINEER

   Business Address: _____

   City, State, Zip: _____

   Phone: _____

   ☐ **Please check if any of the above information has changed since previous year.**

II. *Mining and Reclamation*

1. Was the mine active during the past year? Yes ☐ No ☒
2. If active, how much ore or mineral was mined? _____
3. *If inactive*, what year was the mine **last active**? 1996

3. How much **additional acreage** was disturbed during the past year? NONE

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

N/A

5. How much acreage was **reclaimed** during the past year? NONE

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

N/A

7. What is the **total disturbed acreage** at years end? 20-25 ACRES (EST.)

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

REMOVE CLAY STOCK PILES ONLY

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. *Additional Information*

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.

2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. *Signature Requirement*

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): DARIN OLSON

Title of Operator: FACILITY ENGINEER

Signature of Operator: Darin Olson

Date: 12-17-97

jb
MR-AR