JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 29, 2008

Reviewed _____

Mine Name: Travertine 1	**Permit Number**: M0230042
Operator Name: BEG Resources	**Inspection Date**: March 12, 2008
Inspector(s): L Heppler, T Munson	**Time**: 10:15 am
Other Participants: None	**Mine Status**: INA

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☒	☒	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☒	☐	☐
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☐	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls,	☐	☐	☐
8. Soils	☐	☐	☐
9. Revegetation	☒	☒	☐

Bond Renewal Date: 06-18-2005 **Bond Amount:** $15,100 **Permit fee** is delinquent – need to pay fee

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Nothing has been done to the site since last inspection

Conclusions and Recommendations: The reclaimed area does not meet this revegetation success standard, and the area is not expect to meet this standard without remedial work, reseeding is needed. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature _____

LAH:pb
cc: Gary Burningham – BEG Resources, Inc.
Jerry Mansfield – BLM
Attach - GIS
O:\M023-Juab\M0230042-Begtravertine\inspections\Insp_BEG_03-12-08.doc

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov