STAFF REPORT

TITLE: Photographs of Richard Hilyard's Notice operation (UT-058-45N) MKJ

DATE: May 15, 1990

AUTHOR: Michael Jackson, District Geologist MKJ

These photographs were taken on April 3, 1990, on the date of the site inspection.

Sign Posted to Keep Public Out. Unauthorized.

View North of Site.



Trommel and other equipment. Unreclaimed mounds.

Abandoned bulldozer and road cut marked as new road on amended map for UT-058-1GN.

Road/open cut uphill from dozer in area labeled as new road on amended map.